## 4 ALBERT EMBANKMENT LONDON SE1 7SR

Telephone: +44 (0)20 7735 7611 Fax: +44 (0)20 7587 3210

MSC.1/Circ.1674 27 June 2023

## UNIFIED INTERPRETATIONS OF THE LSA CODE AND THE 1994 AND 2000 HSC CODES

- The Maritime Safety Committee, at its 107th session (31 May to 9 June 2023), with a view to providing more specific guidance on paragraphs 4.1.5.1.13, 4.4.8.16 and 5.1.2.2.7 of the LSA Code; paragraph 3.8.10 of annex 10 to the 1994 HSC Code; and paragraph 3.8.10 of annex 11 to the 2000 HSC Code, approved unified interpretations of the LSA Code and the 1994 and 2000 HSC Codes, prepared by the Sub-Committee on Ship Systems and Equipment, at its ninth session (27 February to 3 March 2023), as set out in the annex.
- Member States are invited to use the annexed unified interpretations as guidance when applying paragraphs 4.1.5.1.13, 4.4.8.16 and 5.1.2.2.7 of the LSA Code; paragraph 3.8.10 of annex 10 to the 1994 HSC Code; and paragraph 3.8.10 of annex 11 to the 2000 HSC Code, and to bring them to the attention of all parties concerned.

\*\*\*



## ANNEX

## UNIFIED INTERPRETATION OF THE LSA CODE AND THE 1994 AND 2000 HSC CODES

Paragraphs 4.1.5.1.13, 4.4.8.16 and 5.1.2.2.7 of the LSA Code – Equipment of liferaft, lifeboat and rescue boat, respectively

Paragraph 3.8.10 of annex 10 to the 1994 HSC Code – Equipment of open reversible liferaft

Paragraph 3.8.10 of annex 11 to the 2000 HSC Code – Equipment of open reversible liferaft

- One spare bulb should be provided for torches utilizing either a filament bulb or single LED to provide the light source. Where the light source is provided by more than one LED, a spare LED bulb is not required, provided the failure of any one LED does not prevent the other LEDs from fully functioning.
- 2 Provision of a second ready-for-use waterproof electric torch suitable for Morse signalling can be accepted as an alternative to providing one spare set of batteries and one spare bulb in a waterproof container.

I:\CIRC\MSC\1\MSC.1-Circ.1674.docx